

# Site Drainage Area



# Attachment 1 - Site Photos



View of eroded areas encroaching on the trail (facing north).



View from trail down along eroded area at STA 63+00



View from trail down along eroded area over the culvert.



# Attachment 7 - Culvert Photos

